

# PLASTIC Flight Operations

November 07- April 08

K. Singer  
SWG April 2008

# PLASTIC Flight Operations

- 12/6/07: DOY 340 on SC B
  - Increase MCP voltage to compensate for normal gain changes
  - 3140V → 3160V
- 12/20/07 DOY 355 SC A & B
  - Changed criteria for Supra-thermal to ignore background events

# PLASTIC Flight Operations

- Flight Software load 3.2.7
  - SC A: DOY 037 (2/7/08)
  - SC B: DOY 063 (3/3/08)
  - RTLT for A: 6 minutes
  - RTLT for B: 7 minutes
  - Bypassed COP1 command counter to reduce the load time


# Software changes

- Included every 10<sup>th</sup> block of the EEPROM read back which was previously missing
- Corrected timestamp on science data packets

- Momentum dumps have gone smoothly—DPU has been disabling and enabling high voltages on Entrance System as necessary.
- Gain on MCP is changing more slowly since initial scrubbing and is stable.
- We are using SECCHI roll calibration data for our own calibration purposes.

# PLASTIC Flight Operations

- SC A: DOY 104 (04/13/08)
  - At 11:58 UT PLASTIC reset



11:58 UT

# PLASTIC Flight Operations


- SC A: DOY 105
  - Start turning on HV's
- SC A: DOY 106-108
  - Continue stepping up HV's
- SC A: DOY 108
  - Start data collection






# SSD Temperatures

# SSD Temperatures since launch SC B




- ~6 degree temperature change since Nov '06
- Delta distance to Sun: 0.1 AU


# ACE Temperatures



- Increase in temperature is due to the degradation of the thermal blanket and not the solar cycle



# SSD Temperatures since launch SC A



- ~11 degree temperature change since Nov '06
- Since January 2007 Delta distance to Sun 0.01 AU
- Exterior radiator

Any questions?